i ke	Work Ord February 3, 20				HAN BINAN BINAN BERK BERK BAN HADI
	Item ID: Revision ID:	D4027-7		Accept	
	Item Name:	Rubber Cushi	ion		
	Start Date: Required Date	2/03/10 e: 2/10/10	Start Qty: 2.00 Req'd Qty: 2.00	1 (10) (0) (10) 1 (10) (10) (10)	Cust Item ID: Customer:
	Reference:		,		
	Approvals:	Process Pla	an:	Date/0-2-03 Tooling	: Date:

Date:___

Start Stop Reject Reject Insp. Number Stamp

Setup Start

Run

Qty

Stop

Page 1

13-10-2-11

Accept

Qty

Quality Control

110

Sequence ID/

Draw Nbr

D4027 100

Waterjet

Work Center ID

FLOW CNC Waterjet

Memo

Memo

1-Cut as per Dwg Dwg Rev: PRE Prog Rev: Lim

2-Deburr if necessary

QC2- Inspect parts off machine FAI/FAIB

Operation

Description

Revision Nbr A-PRELIM

0.00

0.00

SPC (Y/N):

Set Up/

0.00

0.00

Run Hours

Date:

Draw

Rev.

Plan

Code

Draw

Number



Dart Ae	rospace L	td					i		
W/O:	TOSPACE L		WC	ORK ORDER CHANGES					*
DATE	STEP	PR	OCEDURE CHAI	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Ву	Date	Qty Approval Chief Eng / Prod Mgr		Approva QC Inspecto
Part No				gory: N					
	Res	olution:	Disposition	n: Q	A: N/C CI	osed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORMANC	E (NCF	₹)			
DATE	0775	Description of NC			Verifica	aton Approval	Approva		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section		Chief Eng	QC Inspect
							1		
								ţ.	
		*					 		

NOTE: Date & initial all entries

Work Orde February 3, 201								:	Page 2
Item ID: Revision ID: Item Name:	D4027-7 Rubber Cush	ion		Accept			Setup	Start Stop	
Start Date: Required Date: Reference:	2/03/10 2/10/10	Start Qty: 2.00 Req'd Qty: 2.00	1 1141/4 1161 (116) 1 1141/4 1141 (116)		Cust Item ID: Customer:			ļ	
Approvals:	Process Pla	an:	Date:	Tooling: SPC (Y/N):	Date:	 -	Run	Start	
Sequence ID/ Work Center II 120 QC Quality Control	D	Operation Description QC8- Inspect parts - second	ond check	Set Up/ Run Hours 0.00 0.00	Number Rev. (Plan Accep Code Qty	et Rej Qty		Reject Insp. Number Stamp
170 Packaging Packaging		ldentify as per dwg & Sto	ock Location 17	0.00		10	<u>-6-</u>	25	(2) S
180 QC Quality Control		QC21- Final Inspection -	Work Order Release	0.00				V	106/28/19

POSITIVE RECALL EFFECTIVE 16.02-03 AUTH //
RELEASED DATE 1006.23 QLy 2

W/O:			WC	ORK ORDER CHANGES					
DATE	STEP	PR	OCEDURE CHA		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
						F10497		T rod Wigi	
Part No				gory: f					
NCR:				ER NON-CONFORMAN				Date: _	
		December of NO	Corrective Action Section B			1	<u> </u>		T
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verifica Sectio		Approval Chief Eng	Approva QC Inspect
								·	
	1 1		[1		1	I	1

NOTE: Date & initial all entries

Picklist Print

February 3, 2010 1:51:02 PM

Work Order ID: 55880

Parent Item: D4027-7

Parent Item Name:

Comments:

Rubber Cushion

IPP rev A 10.02.01 new issue Prelim EC verified by:JLM

Start Date: 2/03/10

Required Date: 2/10/10

Page 1

Start Qty: 2.00

Required Qty: 2.00

B 10-2-11

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	1	Date Issued	Status
MNEO60S.063		Purchased	No		100	sf	715.1060	0.0860	18			



NEOPRENE SHEET 0.063

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
MAT	715.106		
112508	61.6034		
112662	290.2821		
112866	154.11		
113058	209.1105		113050

Dart Aerospace Ltd W/O: WORK ORDER CHANGES DATE STEP PROCEDURE CHANGE By Date Qty Approval OC Inspector Prod Mgr OC Inspector QC Insp

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:	Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC	Corrective Action Section B			Verifica t on	Approval	Approval		
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C	Chief Eng	QC Inspector		
					:					
							1	ĺ		

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	52880
DART AEROSPACE ETD		
Description: Rubber Curling	Part Number:	D4027-7
Inspection Dwg: Dwg: Dwg: DKELim Pag		Page 1 of 1
Inspection Dwg: 14027 Rev: DISTIM PIS	<u> </u>	

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype	X	First Article	Prototy	pe
---------------------------	---	---------------	---------	----

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
,75	4/030	,758	*	ļ		
8.75	7 .02)	8.269	×			
, 660	1/2 1010	,062	12			
			ļ	 		
				ļ		
		· · · · · · · · · · · · · · · · · · ·				
			· · · · · · · · · · · · · · · · · · ·	-		
	ļ		-	 		
			<u> </u>	-	-	
			 	1		
		+	-			
	-		+	-		
			 			
			 	1		
				+		
	+		 	1		ŷ _y ,
_	+		-			
			1			

Measured by:	12	Audited by:	Prototype Approval:	N/A
Date:	10-2-11	Date: 10/00/16	Date:	N/A

1	_	D-4-	Change Revise	ed by Approve	<u>ea</u>
Ì	Rev	Date	Change KJ/JLM	A	
	Α		New Issue		

/1000-23 pe lev. A.



